FIG. 1A




FIG. 1B




FIG. 2A




FIG. 2B







FIG. 2C










FIG.6A




FIG.6B

AE OPE	ERATION V
PROGRAM	<u> </u>
APERTURI	E PRIORITY
SHUTTER	,-
OFF (MAN	UAL)
SET→SHUT	TER BUTTON

FIG.7A




FIG.7B

AF OPERATION \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
CONTINUOUS AF MODE
SINGLE AF MODE
OFF (MANUAL)
SET→SHUTTER BUTTON

FIG. 8






FIG. 9A


	В	G	В	G		G	в
R	G	R	G	R	G	R	G
G	В	G	В	G	В	G	в
R	G	R	G	R	G	R	G
G	В	G	В	G	В	G	В
	G	R	G	R		R	G
G	В	G	В	G	В	G	в

FIG. 9B

	Ye	G	Υe	G	18/1 4 /1.	G	Ye	•••
Су	Ма	Су	Ma	Су	Ma	Су	Ma	•••
G	Ye	G	Υe	G	Ye	G	Υe	<u></u>
Су	Ma	Су	Ma	Су	Ma	Су	Ma	
G	Ye	G	Υe	G	Ye	G	Υe	•••
14/4/1.	Ma	Су	Ma	Су		Су	Ma	<u> </u>
G	Ye	G	Ye	G	Ye	G	Ye	










FIG.13




FIG.14




FIG.15




FIG.16




FIG. 17 A


G _{1.1}	B _{1,6}	G 1, 11	B 1. 16
R 6, 1	G 6. 6	R _{6.11}	G 6, 16
G11, 1	B _{11.6}	G11, 11	B11,.16
R 16, 1	G 16, 6	R16, 11	G 16, 16


FIG. 17B

Y 1, 1	Y 1. 6	Y 1, 11	Y 1, 16
Y 6, 1	Y 6, 6	Y 6. 11	Y 6, 16
Y 11, 1	Y 11. 6	Y 11, 11	Y 11, 16
Y 16. 1	Y 16, 6	Y 16, 11	Y 16, 16

FIG. 17 C

Y 6, 6	Y 6. 6	Y 6, 11	Y 6, 11
Y 6. 6	Y 6. 6	Y 6, 11	Y 6, 11
Y 11. 6	Y 11, 6	Y 11, 11	Y 11, 11
Y 11. 6	Y 1 1, 6	Y11, 11	Y11, 11








FIG.21




FIG.22




FIG.23









FIG.24














START

S501

VES

DISTANT VIEW MODE
OR RANGERING AT

POSITION?

S502

CLEAR PEAKING MODE

END

START

S501

NO
S503

SET PEAKING MODE

FIG.30 START S511 YES **CONTINUOUS AF MODE?** S512 NO **CLEAR PEAKING** NO(MANUAL) MODE SINGLE AF MODE? S514 S513⁻ YES **SET PEAKING END** MODE **CLEAR PEAKING MODE** S515⁻ **END** AF OPERATION S516 S517 FOCUSED? YES **SET PEAKING MODE** S518~ DISPLAY SUBJECT IN PEAKING MODE S519 **END**

